



OHMS BETWEEN TIP AND SLEEVE, WITH TRIM ON "0", SHOULD BE 9K ALWAYS
 OHMS BETWEEN RING AND SLEEVE, WITH TRIM ON "0", SHOULD VARY FROM 9K/HEEL DOWN, TO 0 OHMS/TOE DOWN

E	D	C	B	A	Draun	9/20/10	Check	RAD	Projection	Do Not Scale	Client	GODLYKE	Projection	Do Not Scale	Client	Filename	File Name	Expression Pedal for Triskellion	Drawing No.	Sheet	of	
Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn	Drn
Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk	Chk